

# Oil Field Environmental Incident Summary

**Incident:** 20161108155011      **Date/Time of Notice:** 11/08/2016 15:50  
**Responsible Party:** BURLINGTON RESOURCES OIL & GAS COMPANY LP  
**Well Operator:** BURLINGTON RESOURCES OIL & GAS COMPANY LP  
**Well Name:** KIRKLAND/MORGAN QUAD PAD  
**Field Name:** PERSHING      **Well File #:**  
**Date Incident:** 11/7/2016      **Time Incident:** 17:10      **Facility ID Number:** 222789-01  
**County:** MCKENZIE      **Twp:** 150      **Rng:** 96      **Sec:** 28      **Qtr:** NE NW  
**Location Description:** A light mist travelled off the East side of location

**Submitted By:** Josey Adams      **Received By:**  
**Contact Person:** Josey Adams  
600 N. DAIRY ASHFORD  
HOUSTON, TX 77079

**General Land Use:** Well/Facility Site      **Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 3280 Feet  
**Distance Nearest Water Well:** 3280 Feet

**Type of Incident:** Other

**Release Contained in Dike:** No

**Reported to NRC:** No

|            | <b>Spilled</b> | <b>Units</b> | <b>Recovered</b> | <b>Units</b> | <b>Followup</b> | <b>Units</b> |
|------------|----------------|--------------|------------------|--------------|-----------------|--------------|
| <b>Oil</b> | 15             | Gallons      | 15               | Gallons      | 15              | gallons      |

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 12/22/2016      **Clean Up Concluded:** 11/8/2016

**Risk Evaluation:**  
Soil contamination

**Areal Extent:**  
Misted East side of location

**Potential Environmental Impacts:**

Soil contamination

**Action Taken or Planned:**

Work order put in to recover contaminated soil

**Wastes Disposal Location:** Local waste facility. Tervita

**Agencies Involved:**

**Updates**

---

**Date:** 11/8/2016    **Status:** Reviewed - Follow-up Required

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release impacted areas off location. Follow-up is required.

---

**Date:** 11/14/2016    **Status:** Inspection

**Author:** Wax, Pete

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

On site at 16:13. Clear, light wind from the SW, 56 degrees. Nearest water approximately 75 meters to the east. Walked entire outside perimeter of the pad. Flushed partridge and mule deer but found no evidence of spray off the well pad site. Off site at 16:32.